



MID WHEELS V25

V25

○ Spec



Metallic Gray(MGR)



Metallic Gray(MGR)

Product Name	V25
Size	12inch/13inch/14inch/15inch/16inch/17inch/18inch
Construction Method	Cast 1pc. Wheel Made in China
Safety Standards	JWL VIA compliant *12 and 13 inches are JWL-T compliant
Color	Metallic Gray(MGR)
Included	Center cap, valve
Optional	Center cap ¥3,000 (ex. tax), valve ¥400 (ex. tax)

Prices are noted in Japanese YEN(JPY). Specifications in the English version are intended for customers outside of Japan and do not include Japan sales tax.

SIZE	INSET (): HUB CLEARANCE (mm)	HOLE	P.C.D.	HUB BORE (φ)	DRILL (φ)	PRICE	CALIPER CLEARANCE	DISK PROTRUSIO N (mm)
						MGR		
12x4B	42(33)	4	100	67	32-13	16,000	-	10.9
13x4B	43(33)	4	100	67	32-13	16,500	-	13
13x4.5B	50(23)	4	100	67	32-13	17,000	****	8.5
13x5B	35(38)	4	100	67	32-13	17,500	-	6
14x4.5J	50(28)	4	100	67	32-13	18,500	****	9.9
	45(33)						***	
14x5.5J	45(35)	4	100	67	32-13	19,000	-	7
	38(42)							
15x4.5J	45(33)	4	100	67	32-13	20,500	-	9.9
15x5.5J	50(35)	4	100	67	32-13	21,500	-	10
	45(40)							
	40(45)							
15x6J	45(44)	5	100	67	32-13	22,000	-	9
	44(45)			54	33-19		★1	
	52(36)		114.3	73	32-13		-	
	51(38)			60	33-19		★2	
	45(44)			73	32-13		-	

15x6.5J	40(38)	5	100	54	33-19	22,500	★1	3	
16x6J	43(35)	4	100	67	32-13	25,500	-	3.9	
		5							
16x6.5J	53(39)	5	114.3	73	32-13	26,000	-	7	
	48(44)								
	38(54)								
	37(55)			60	33-19		★2		
17x7J	48(45)	5	100	67	32-13	30,500	-	5	
	55(38)		114.3	73			**		
	48(45)						60		33-19
	38(55)				★2				
	47(46)			★2,**					
	37(56)								
18x7.5J	53(35)	5	114.3	73	32-13	36,000	-	3	
	38(50)						**		

Caution

** The marked inset is a model for Crown 3.5L big calipers.

***The mark indicates models compatible with Solio and Delica D:2 calipers.

****The inset marked is the Every caliper compatible model.

★1/★2 Mark is exclusively for Toyota flat seat nuts, featuring a dedicated hub-centric type. Please take note.

16 to 18-inch wheels are compatible with the air sensor valves of LEXUS, V37 Skyline (only 17/18-inch), and E52 Elgrand.

This product has the disk protruding beyond the rim, so please take care when installing.